



INSTRUCTIONS

KEEP FOR REFERENCE.

Read manual 308611 for important warnings and instructions.

2nd Stencil Gun Kit

Model 238958, Series A

Pressure Relief Procedure


WARNING



INJECTION HAZARD

The system pressure must be manually relieved to prevent the system from starting or spraying accidentally. Fluid under high pressure can be injected through the skin and cause serious injury. To reduce the risk of an injury from injection, splashing fluid, or moving parts, follow the **Pressure Relief Procedure** in manual 308611 whenever you:


- are instructed to relieve the pressure,
- stop spraying,
- check or service any of the system equipment,
- or install or clean the spray tip.



06535

Installation

1. Relieve pressure. See **Pressure Relief Procedure**.
2. Refer to Fig. 1 for reference numbers.
3. See cover. Connect gun holder (3) to frame with bar lock (5), screws (7) and lock nuts (8).
4. Secure flex gun (4) in gun holder (3) with pronged knob (1).



Parts List

Ref. No.	Part No.	Description	Qty
1	181818	KNOB, pronged	1
2	181795	JAW, clamp	1
3	188452	HOLDER, gun	1
4	246467	FLEX GUN	1
5	191869	BAR, lock	1
6	191238	HOSE, coupled, 1/4 x 50 ft	1
7	103547	SCREW, mach, hex hd	2
8	102040	NUT, lock	2
9	108483	SCREW, shoulder,	2
10	186335	NUT, gun	1
11	223718	TUBE, extension, 15.83 in.	1
12	186334	ADAPTER, tip	1
13	237852	GUARD, RAC	1
14	286425	SwitchTip, size 425	1
15	166969	GASKET	1

Graco Phone Number

TO PLACE AN ORDER, contact your Graco distributor, or call this number to identify the distributor closest to you: **1-800-690-2894 Toll Free**

Fig. 1

06534A

All written and visual data contained in this document reflects the latest product information available at the time of publication. Graco reserves the right to make changes at any time without notice.

Sales Offices: Minneapolis, Detroit
International Offices: Belgium, Korea, Hong Kong, Japan

GRACO INC. P.O. BOX 1441 MINNEAPOLIS, MN 55440-1441

<http://www.graco.com>

PRINTED IN U.S.A. 308681 September 1996, Revised 12/2003